

Osprey Platform Material List

Pole	1	16'	6" x 6" Pressure Treated
Box Frame	1	12'	2" x 6" Pressure Treated
Platform Base	1	5'	2" x 6" Pressure Treated
Perch Base	2	8'	2" x 6" Pressure Treated
Side Supports	1	3'	5/4" x 6" Pressure Treated (Ripped)
Hardware Cloth	1	3' Square	1/4" Galvanized
Fasteners			
Platform Base to Pole	8	3/8" x 6"	Galvanized Lag Bolts
	2	3/8"	Galvanized Flat Washers
Box to Platform Base	8	#8 x 3"	Galvanized Drywall Screws (3.99/lb.) or 12 Lb. Galvanized Nails
Four Corners of Box	12	#8 x 3"	Galvanized Drywall Screws or 12 Lb. Galvanized Nails
Perch Brace to Platform Brace	2	3/8" x 8"	Galvanized Carriage Bolts
	2	3/8"	Galvanized Washers
Perch Braces to Pole	1	1/2" x 10"	Galvanized Hex Bolt
	2	5/8"	Galvanized Flat Washers
Fasten Wire to Box	40	3/8"	Galvanized Fence Staples (1.20/lb.)
Side Supports to Box	8	8b	Galvanized Nails (1.19/lb.)

All poles must have a predator guard!

Osprey Platform Diagram

